

WAI - 12189N - ALTERNADOR THERMO KING 12V 40A

Agco (2000-2006) , Aixam (2005-2015) , Aixam - Europe (2000-2012) , Daihatsu - Europe (1985-2000) , Daihatsu LCV - Europe (1986-1998) , Ford (1995-1999) , Ishikawajima (1987-1992) , Kubota (1986-2007)

Massey Ferguson (1993-1999) , New Holland Industrial (1995-2008) , Thermo King (1991-1991)

021080-0760;100211-4690

Daihatsu Motor Co 27060-87201, 27060-87201-000, 27060-87501, 27060-87502-000, Denso 021080-0760, 100211-1610, 100211-1611, 100211-1630, 100211-1640, 100211-1650, 100211-1680, 100211-4450, 100211-4660, 100211-4690, 100211-6780, 101211-1060, 101211-1290, 101211-1310, 101211-2480, 18504-6430, Ford SBA18504-6220, Iseki 6281-200-005-0, 6281-200-005-4, Ishikawajima 18504-6220, 18504-6430, Kubota 15881-64200, 15881-64201, 17580-64012, PH101-81401, New Holland SBA18504-6220, Thermo King 41-0749, 5D36221G01, Valeo 436497 12189, 12189A, 12271

