

WAI - 16739N - ARRANQUE THERMO KING 2.0KW 9T 12V 0280007790

Chevrolet (1981-1985) , Elgin Sweeper (1989-1993) , Gehl (1984-1994) , GMC (1984-1985) , Hyster (1980-2006) , Isuzu (1976-2001) , John Deere (1977-1984) , Thermo King (1974-1997)

Carrier Transicold 20-44-1285, 20-44-5674, Cummins 3675152RX, Denso 028000-5060, 028000-6440, 028000-6441, 028000-7000, 028000-7001, 028000-7002, 028000-7003, 028000-7004, 028000-7790, 028000-7791, 128000-0020, 128000-0021, 128000-0022, 128000-0960, 128000-2880, 128000-2881, 128000-3100, 128000-3101, 128000-4660, 128000-4661, 228000-1120, 228000-1121, 228000-1122, 228000-4290, 228000-4291, 228000-4292, 228000-4293, GM 94030241, 94123387, Hitachi S114-371, S114-371A, S114-371B, S12-48, S12-58, Hyster 1374083, 323812, Iseki 6281-100-001, 62811000100A, 62811000101E, Isuzu 2912559140, 5811000571, 5811000860, 5811000990, 5811000991, 5811001550, 5811001660, 5811001661, 5811001662, 5811001663, 5811001664, 5811001830, 5811001831, 8941233870, 8941492490, 8944127300, 8944127301, 8944489590, 8944489591, 8970489650, 8970489651, 8970489652, John Deere AM108722, GV11567, Komatsu 600-813-1750, 600-861-1750, Thermo King 44-5674, 45-1229, 45-5657, 45-56572, 45-5674 16739, 18298, 19745, 19788, 30055

