

ECLIMA - 122876 - COMPRESOR DENSO TOYOTA HILUX-HIACE 2.5D4D PK7 120MM 12V

8832026600 / 88320-2F060 / 88320-25110 / 88310-0K270 / 88310-25220 / 88320-26600 / 883202F060 /
8832025110 / 883100K270 / 8831025220 / 447220407 / 4472204071/ 4472204072/ 4472204073 / 447220-
4472

447220-4072, 447220-4071, 447280-0750, 447220-4470, 447220-4242, 447220-4471, 447170-9510,
447220-4241, 447220-4070, 447220-4240, 447220-4070, 447220-4071, 447220-4072, 447220-4073,
4472204472, 4472204073, 4472204072, 4472204071, 4472800750, 4472204470, 4472204242,
4472204471, 4471709510, 4472204241, 4472204070, 4472204240

8832035730 88320-28410 88320-6A081 8832028410 88410-35400 883206A081 8831028550 88310-
28550 88310-6A141 883106A140 8841035400 88310-6A140 883106A141 883206A081, 883206A080
DCP50085 447260-6250 447220-5261 ACP315 700510216 51-0216 447220-5260 447300-9271 447220-
5261

